LMA District Cover Sheet

Spring 2016 Levee Inspection Results

Sutter Maintenance Yard Murphy Slough at M&T Ranch

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				
	** Non-receipt of Su	mmer or Winter Inspe	ection Reports may effec	ct overall annual rating.
* SPRING INSPECTIONS: Overall maintenance deficiencies are rated	ratings are not detern d using the same crite			ual maintenance
FALL INSPECTIONS: The overall maintena within the attached u			ion and maintenance de inded to be an indiction o	
Comments				

Unit Cover Sheet

Spring 2016 Levee Inspection Results

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/15/2016 - 4/15/2016			
DWR Inspector	Keith Millard			
Accompanied By	Jason Cooper Sutter Maintenance Yard			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

http://cdec.water.ca.gov/lma.html

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Levee Inspection Report By Mile - Spring 2016

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83	04/15/2016 04/15/2016	Keith Millard

		D (' **		I N			
LM Start		Rating **	Α	Issue No.		2	
LM End		Issue Type +	Ma	Location *		N/A	
Category	Earthen L	evee		GPS La	atituc	de/Longitude	
Category				Start		End	
Item	Operations & Maintenance				0		0
пеш	Manuals				0		0
DWR ID DWR_NA0014_01_s _ 2013_2							
Comment Code							
Inspector Comment							
The LMA completed flood fight training in 2014.							

No Photos

LM Start		Rating **	Α	Issue No.		3		
LM End		Issue Type +	Ma	Location *		N/A		
Category	Earthen L	evee		GPS La	atitud	e/Longitude		
Calegory				Start		End		
Item Emergency Supplies & Equipment				0		0		
					0		0	
DWR ID	DWR_NA0	014_01_s _ 201	3_3					
		Comn	nent Cod	de				
Inspector Comment								
The LMA h	The LMA has adequate flood fight supplies and equipment.							
l .								

No Photos

LM Start		Rating **	Α	Issue No.		6	
LM End		Issue Type +	Ма	Location *		N/A	_
Cotogony	Earthen L	evee		GPS La	atituc	le/Longitude	
Category				Start		End	
Item	Flood Pre	paredness &		0		0	
пеш	item				0		0
DWR ID DWR_NA0014_01_s _ 2013_6							
		Comn	nent Cod	le			
		Inspecto	or Comm	ent			
There is no O&M Manual for M&T Ranch.							

No Photos

* Location	** Rating		+ Issue Type
LS : Land Side N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiancy
WS: Water Side	M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En: Enforcement

Levee Inspection Report By Mile - Spring 2016

Sutter Maintenance Yard Murphy Slough at M&T Ranch

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Murphy Slough at M&T Ranch	Left	0.83	04/15/2016 04/15/2016	Keith Millard

LM Start	0.00	Rating **	М	Issue No.		1
LM End	0.09	Issue Type +	Ма	Location *		WS
Category	Earthen L	evee		GPS La	atitud	le/Longitude
Calegory				Start		End
Item	Vegetatio	n		39.6675	34°	39.666836°
пеш			-121.959612 °		-121.960897°	
DWR ID DWR_NA0014_01_s _ 2012_1						
		Comn	nent Cod	le		
V4 : Elderk	perries are	blocking visib	ility and	flood fight	сара	ability.
			_			
		Inspecto	or Comm	ent		

No Photos

LM Start	0.00	Rating **	М	Issue No.		4	
LM End	0.09	Issue Type +	Ma	Location *	LS		
Category Earthen Levee				GPS La	titud	e/Longitude	
				Start		End	
Item	Vegetation			39.66770	08°	39.666983°	
item				-121.959817°		-121.960997 °	
DWR ID DWR_NA0014_01_s _ 2012_4							
Comment Code							
V4 : Elderberries are blocking visibility and flood fight capability.							

Inspector Comment

No Photos

N: Not Inspected/Rated C: Corrected A/W: Acceptable but Monitor & Maintain + Issue Type

Ma : Maintenance Deficiancy
Ob : Design & System Obsolescence
En : Enforcement